

FEATURE

- The Digital Tachometer provides fast and accurate Contact and Non-Contact RPM and surface speed measurements of rotating objects.
- Measurement type: Rotation Speed (RPM, rPm), Total revolutions (REV), Frequency (HZ), Surface Speed (M/M, I/M, F/M, Y/M) and Length (M, In, FT, Yd).
- Wide measure range and high resolution.
- High visible digital LCD and Backlight display.
- 40 reading memories : 10 selectable MAX measurements, 10 selectable MIN measurements, 10 selectable AVG measurements, 10 selectable DATA measurements.
- Laser sighting.

SPECIFICATIONS

Display	5 digits LCD display.
Accuracy	± (0.05% + 1 digits).
Contact Test range	2 to 20,000RPM
Non-Contact Test range	2 to 99,999RPM
Tot test range	1 to 99,999.
Resolution	0.1 RPM (2 to 9999.9 RPM). 1 RPM. (over 10000 RPM)
Sampling time	0.5 sec. (over 120 RPM)
Detecting distance	50mm to 500 mm.
Time base	Quartz crystal
Power consumption	Approx 45mA
Battery	9V
Operation temp	0 °C to 50 °C (32 to 122 °F)

OPTIONAL ACCESSORIES

Mains Adaptor for 230V AC mains operation.



*Technical Specifications & Appearance are subject to change without prior notice